

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-2008
Inspection Date: 2026-06-10
Inspection Outcome: Inspected

Inspection Comment:

3 wellheads only.

All wellhead valves chained and locked.

All signs and surface casing vents compliant.

No leaks detected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078509
Well ID: 29071
Well Name: PETRONAS HZ BUCKINGHORSE D- 060-F/094-G-07
Location: NTS: D- 060-F/094-G-07

Permit: 100079093
Well ID: 29708
Well Name: PETRONAS HZ BUCKINGHORSE D-A060-F/094-G-07
Location: NTS: D-A060-F/094-G-07

Permit: 100079094
Well ID: 29709
Well Name: PETRONAS HZ BUCKINGHORSE D-B060-F/094-G-07
Location: NTS: D-B060-F/094-G-07

Authorized by BCER