

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-2012  
Inspection Date: 2026-06-11  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Inspection with the operator June 9th & 11th, 2026 of pipeline construction, AD 100120913, P 26785 and AD 100107991, P 25243.

The following QC items were reviewed with the contractor. Welding procedures (repairs included), welder declarations, certifications and PQR's. Welding inspector certifications. Radiography Technician certifications, daily reports and NDE log. Repair rate to the date of inspection is 0.46%, with 0% in fabrication. Coating operator certifications to manufacturer and Sureline specifications. Coating inspector certifications. peel tests 1/50 or 1/day/coater, daily coating report and NDE log. Holiday detection, jeepers calibrated daily, voltage to manufacturer specifications, daily reports to NDE log. ITP,s, stringing and pipe tallies, bending, Flex steel deploying report, trenching, lowering in, backfill,

AD 100170991, P25243. The ROW has been cleared, 12" pipe is strung, welded and on blocks. There is an existing hot line in proximity to the 12" line that has been located daylighted approximately every 30 meters. The HDD is setting up for hot line crossing, the drill execution plan, profile, environmental plan produced on site. The hot line has been located and daylighted. Operator states a 6" flex steel line is planned to be put into the ditch with the 12". Discussed with the operator that the 6" flex steel line is not included in the permit. Tourmaline engineering provided email verification that they are in the process of completing the paperwork to formalize the change, and that the change has been captured on all engineering stamped documents and will be submitting with the as-built.

AD 100120913, P26785.

Shoefly Road, a two wide rig matt road has been constructed on an older non-tenured logging road, without permitting in place. Operator states that they have followed the guidance of the BCER Energy Resource Activity Application Manual Chapter 4.5. The old road is approximately one kilometer long, has a ditch for drainage along one side and was clear of trees. The road starts off the ROW at crossing 12 (GPS 56 40 44N, 122 2 33W) and goes to the B-24-I access road at (GPS 56 41 13N, 122 2 27N). There are two areas where ESC has been installed to control sediment laden water along the shoefly, GPS 56 40 58N, 122

2 37W, at the time of the inspection has sediment laden water and sediment deposited past the ESC into the treeline. The second location is at GPS 56 40 49N, 122 2 36W, and at the time of inspection had effectively contained the sediment. See non-compliance. Additionally, this matter has been referred to the BCER Manager of Enforcement for additional follow-up.

KP 3+300, woody debris has been placed off ROW along the North side onto Crown land from approximately KP 2+300 to KP 3+400. Operator states it was done due to inadequate space on the ROW. Tourmaline Regulatory has been contacted to establish expectations for future pipeline construction and off ROW work or activity.

KP 3+300, Soil piles have been placed on Alta Gas ROW. Operator states that an agreement is in place to utilize the Alta Gas ROW.

KP 3+500, pump off to the Alta Gas ROW, using filter bag. Operator states Alta Gas has given permission for the pump off to their ROW.

Crossing 13, chance find for amphibians, found adult frogs then tadpoles in wet area. Exclusion fencing was installed and daily checks are conducted in work areas to ensure amphibians are not present. Operator states they have applied for a salvage permit.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100107991

Pipeline Project ID: 000025243

Segment IDs (Location): 1 (From NTS: A- 021-I/094-B-09 To NTS: D- 001-I/094-B-09), 5 (From NTS: A- 021-I/094-B-09 To NTS: D- 001-I/094-B-09)

Permit: 100120913

Pipeline Project ID: 000026785

Segment IDs (Location): 1 (From NTS: B- 027-I/094-B-09 To NTS: D- 001-I/094-B-09), 2 (From NTS: B- 027-I/094-B-09 To NTS: D- 001-I/094-B-09), 3 (From NTS: B- 027-I/094-B-09 To NTS: D- 001-I/094-B-09)

Permit: 100107991

Permit: 100120913

Permit Holder: Tourmaline Oil Corp.



Inspection Number: 2026-2012  
Inspection Date: 2026-06-11

Letter ID: L2602848  
Letter Date: 2026-06-16

---

Authorized by BCER