

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2015
Inspection Date: 2026-06-12
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Some surface casing vent containment bins are overflowing and causing staining on the ground. These are not being managed properly. They will be addressed in the body of the inspection.

Meter runs including orifice plates are over due for service/calibration and if meters have satisfied the requirement for exemption to the annual service/calibration the orifice plate still needs to be inspected more frequently than the exemption period.

The tank farm and horizontal separator are out of service.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073958
Well ID: 27333
Well Name: CNRL HZ ALTARES 01-31-083-25
Location: DLS: 01-31-083-25

Permit: 100073970
Well ID: 27334
Well Name: CNRL HZ ALTARES A01-31-083-25
Location: DLS: A01-31-083-25

Permit: 100073971
Well ID: 27335
Well Name: CNRL HZ ALTARES B01-31-083-25
Location: DLS: B01-31-083-25

Permit: 100073972
Well ID: 27337
Well Name: CNRL HZ ALTARES 16-30-083-25
Location: DLS: 16-30-083-25

Permit: 100073973
Well ID: 27338
Well Name: CNRL HZ ALTARES A16-30-083-25
Location: DLS: A16-30-083-25

Permit: 100073974
Well ID: 27339
Well Name: CNRL HZ ALTARES B16-30-083-25
Location: DLS: B16-30-083-25

Permit: 100073975
Well ID: 27340
Well Name: CNRL HZ ALTARES C16-30-083-25
Location: DLS: C16-30-083-25

Permit: 100073999
Well ID: 27336
Well Name: CNRL HZ ALTARES C01-31-083-25
Location: DLS: C01-31-083-25

Permit: 100077585
Well ID: 29021
Well Name: CNRL HZ ALTARES D01-31-083-25
Location: DLS: D01-31-083-25

Authorized by BCER