

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-2019
Inspection Date: 2026-06-11
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-H2O injection with cover. Wellhead valves chained and locked. Flowline is disconnected from the wellhead. No SCVF

-location signage at the beginning of the lease road off of the cecil lake road is missing the flammable symbol. Location signage at the well is compliant.

-lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001215
Well ID: 00939
Well Name: WHITECAP ET AL BOUNDARY 16-32-084-13
Location: DLS: 16-32-084-13

Authorized by BCER