

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-2021
Inspection Date: 2026-06-11
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

This inspection is for the Altares Road , road #1187 segment #1 with focus on the bridge stream crossing at approximately km 2.1. There are a couple of issues found during the inspection with the stability of the road prism and ditch line erosion into the stream. This stream is a tributary to Groundbirch Creek which has populations of artic grayling, bull and rainbow trout according to the BC Government data base found on Habitat Wizard. Photos are in the notebook section.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100056753
Road Number: 01187
Segment IDs (Location): 001 (From NTS: A- 063-G/094-B-08 To NTS: C- 054-G/094-B-08)

Authorized by BCER