

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2044
Inspection Date: 2026-06-16
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA#10093 June 16, 2026: 9:08 hrs.

Wellhead: surface casing valve is in the open position, SCV flow measured no LEL (Altair-5x), SCV no fill/flow observed. Flowlines are partially disconnected to wellhead with valve handles chained and locked.

KERMIT last gas production date: 2023-10. (Suspended status - flowline is not disconnected/isolated).

Posted signage is compliant to standards.

Well Building: Out of service - no current meter/orifice records found on site.

Storage: metal tanker (1x), earth berm containment is in place/functional, SDS labels present, and grounded.

Flowline: Th main flowlines were disconnected from the wellhead; plunger lift is still connected flowline leading to well building to pipeline (not disconnected/blinded).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100019514
Well ID: 10093
Well Name: CNRL HZ HELMET A- 093-F/094-P-15
Location: NTS: A- 093-F/094-P-15



Inspection Number: 2026-2044
Inspection Date: 2026-06-16

Letter ID: L2602908
Letter Date: 2026-06-19

Authorized by BCER