

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2045
Inspection Date: 2026-06-17
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to Tourmaline HZ Monias 09-18-82-21 location sign in site orientation.
- * meet with site supervisors discuss operations, review documents
- * rig currently laying down drill pipe.
- * conduct walk around and visual inspection.
- * discuss inspection, no concerns at the time of completing this inspection.
- * sign out return to Dawson Creek

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100119911
Well ID: 55745
Well Name: TOURMALINE HZ MONIAS H09-18-082-21
Location: DLS: H09-18-082-21

Authorized by BCER