

## Inspection Report

Permit Holder: Cavvy Production Ltd.  
Inspection: 2026-2067  
Inspection Date: 2026-06-18  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Well is Active.

Sign and surface casing vent compliant to standards.

Well cabinet and chem tank/containment compliant. All critical valves secured.

Comment:

1. Corton fluid from wildfire damaged chem tank observed on ground below chem tank containment, around meter box/flowlines and migrating beyond the immediate spill area. Impacted small area of ponded water nearby shows murky water and signs of wildlife activity in the soft ground at the waters edge. See photos in Gallery. Email with request for information on the spill event and followup actions sent to Cavvy.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040327  
Well ID: 17116  
Well Name: CAVVY HZ EKWAN B- 039-F/094-I-10  
Location: NTS: B- 039-F/094-I-10

Permit: 100040327  
Facility ID: 00020516  
Facility Name: CAVVY EKWAN B-039-F/094-I-10 001  
Facility Type: Well Facility  
Location: NTS: B- 039-F/094-I-10



Inspection Number: 2026-2067  
Inspection Date: 2026-06-18

Letter ID: L2602953  
Letter Date: 2026-06-22

---

Authorized by BCER