

## Inspection Report

Permit Holder: Strathcona Resources Ltd.  
Inspection: 2026-2106  
Inspection Date: 2026-06-23  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1315HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well: Wellhead Abandoned. Surface equipment removed from site. Location has been seeded and reclaimed (See attached). Location has been planted. Company representative unsure if COR has been submitted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100015149  
Well ID: 08490  
Well Name: STRATHCONA ET AL RIGEL 13-14-088-18  
Location: DLS: 13-14-088-18

Permit: 100020712  
Facility ID: 00002681  
Facility Name: STRATHCONA RIGEL 13-14-088-18 001  
Facility Type: Battery Site  
Location: DLS: 13-14-088-18

Permit: 100021664  
Facility ID: 00002833  
Facility Name: STRATHCONA RIGEL 13-14-088-18 002  
Facility Type: Satellite Battery  
Location: DLS: 13-14-088-18



Inspection Number: 2026-2106  
Inspection Date: 2026-06-23

Letter ID: L2603013  
Letter Date: 2026-06-25

---

Authorized by BCER