

Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-2110
Inspection Date: 2026-06-23
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1350HRS.

Access road- No concerns at the time of inspection.

Lease environment- Dead vegetation on lease (Sprayed). No erosion sediment or water runoff concerns.

Lease Equipment: Well: Wellhead Abandoned. Surface equipment removed from site. Signage at entrance. Site has recently been sprayed for weeds (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100021473
Well ID: 10957
Well Name: STRATHCONA ET AL RIGEL 02-28-088-18
Location: DLS: 02-28-088-18

Permit: 100021473
Facility ID: 00019342
Facility Name: STRATHCONA BUICKCREEK 02-28-088-18 001
Facility Type: Well Facility
Location: DLS: 02-28-088-18

Permit: 100021888
Facility ID: 00002908
Facility Name: STRATHCONA RIGEL 02-28-088-18 002
Facility Type: Battery Site
Location: DLS: 02-28-088-18

Permit: 100022310
Facility ID: 00003019
Facility Name: STRATHCONA RIGEL 02-28-088-18 003
Facility Type: Satellite Battery
Location: DLS: 02-28-088-18

Permit: 100022792
Facility ID: 00003213
Facility Name: STRATHCONA RIGEL 02-28-088-18 004
Facility Type: Battery Site
Location: DLS: 02-28-088-18

Authorized by BCER