

Inspection Report

Permit Holder: Kelt Exploration (LNG) Ltd.
Inspection: 2026-2112
Inspection Date: 2026-06-23
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1410HRS.

Access road- No concerns at the time of inspection.

Lease environment- Dead vegetation on lease (Sprayed). No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Site has recently been sprayed for weeds

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100115255
Well ID: 45172
Well Name: KELT LNG HZ MUSKRAT 11-26-087-18
Location: DLS: 11-26-087-18

Authorized by BCER