

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-2127  
Inspection Date: 2026-06-24  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1145HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (one flow line removed). Valve Handle chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016576  
Well ID: 09008  
Well Name: TOURMALINE MARTIN D- 041-E/094-H-06  
Location: NTS: D- 041-E/094-H-06

---

Authorized by BCER