

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2129
Inspection Date: 2026-06-24
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1245HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handle chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Insulation wrap fallen off wellhead and laying on ground (See attached).

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site- containment structure starting to bow but still holding fluid (See attached). No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100049573
Well ID: 19928
Well Name: TOURMALINE MARTIN D- 095-D/094-H-06
Location: NTS: D- 095-D/094-H-06

Permit: 100049573
Facility ID: 00021456
Facility Name: TOURMALINE MARTIN D-095-D/094-H-06 001
Facility Type: Well Facility
Location: NTS: D- 095-D/094-H-06

Authorized by BCER