

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2132
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations. Wells conform to suspended well legislation.

Note: Chem pump operating with cover removed and should be corrected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055274
Well ID: 21528
Well Name: OVV SWAN 05-23-077-15
Location: DLS: 05-23-077-15

Permit: 100060218
Well ID: 22891
Well Name: OVV ECOG HZ SWAN A05-23-077-15
Location: DLS: A05-23-077-15

Permit: 100060219
Well ID: 22892
Well Name: OVV ECOG HZ SWAN B05-23-077-15
Location: DLS: B05-23-077-15

Permit: 100066158
Well ID: 24710
Well Name: OVV ECOG HZ SWAN D05-23-077-15
Location: DLS: D05-23-077-15

Permit: 100066159
Well ID: 24711
Well Name: OVV ECOG HZ SWAN C05-23-077-15
Location: DLS: C05-23-077-15

Permit: 100055274
Facility ID: 00022272
Facility Name: OVV HERITAGE 05-23-077-15 001
Facility Type: Well Facility
Location: DLS: 05-23-077-15

Permit: 100060218
Facility ID: 00022847
Facility Name: OVV HERITAGE 05-23-077-15 003
Facility Type: Well Facility
Location: DLS: 05-23-077-15

Permit: 100060219
Facility ID: 00022848
Facility Name: OVV HERITAGE 05-23-077-15 004
Facility Type: Well Facility
Location: DLS: 05-23-077-15

Permit: 100066158
Facility ID: 00023808
Facility Name: OVV HERITAGE 05-23-077-15 007
Facility Type: Well Facility
Location: DLS: 05-23-077-15

Permit: 100066159
Facility ID: 00023809
Facility Name: OVV HERITAGE 05-23-077-15 008
Facility Type: Well Facility
Location: DLS: 05-23-077-15

Authorized by BCER