

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2135
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations. 4-17 well conforms to suspended well legislation.

Note: D-4-17 wellhead barricade missing and should be replaced.

4-17-77-14 shows as active in the system but is actually suspended. Production records indicate last production was 11/2024 so paperwork to suspend well needs to be completed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043876
Well ID: 18288
Well Name: OVV BISSETTE 04-17-077-14
Location: DLS: 04-17-077-14

Permit: 100066227
Well ID: 24775
Well Name: OVV ECOG HZ HERITAGE A04-17-077-14
Location: DLS: A04-17-077-14

Permit: 100066245
Well ID: 24787
Well Name: OVV ECOG HZ HERITAGE B04-17-077-14
Location: DLS: B04-17-077-14

Permit: 100081105
Well ID: 30754
Well Name: OVV CRP HZ SWAN C04-17-077-14
Location: DLS: C04-17-077-14

Permit: 100081106
Well ID: 30755
Well Name: OVV CRP HZ SWAN D04-17-077-14
Location: DLS: D04-17-077-14

Permit: 100081107
Well ID: 30756
Well Name: OVV CRP HZ SWAN E04-17-077-14
Location: DLS: E04-17-077-14

Permit: 100081108
Well ID: 30757
Well Name: OVV CRP HZ SWAN F04-17-077-14
Location: DLS: F04-17-077-14

Permit: 100083473
Facility ID: 00018305
Facility Name: OVV SWANLAKE 04-17-077-14 002
Facility Type: Well Facility
Location: DLS: 04-17-077-14

Authorized by BCER