

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-2138
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to CVE ENERGY HZ SWAN LAKE B- 073-J/093-P-08, sign in site orientation.
- * Meet and greet with site supervisors.
- * discuss operations, currently circulating prior to tripping out of hole to run surface casing.
- * discuss ERP meeting process.
- * conduct walk around site and look at the drilling rig.
- * discuss walk around and what was seen.
- * Incinerator placement as per Drilling and production regulations 47 Fire prevention (C) flares and incinerators are located at least (ii) 80 m from any other public road. discuss options.
- * A full inspection will happen once BOP are installed, pressure tested and drilling ahead has resumed.
- * sign out return to Dawson Creek

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100121168
Well ID: 56620
Well Name: CVE ENERGY HZ SWAN LAKE B- 073-J/093-P-08
Location: NTS: B- 073-J/093-P-08

Permit: 100121168
Permit Condition:
Critical features are identified within the EPZ, Pre-sour actions must be reviewed and carried out per the BC Energy Regulator ERP Review Meeting Checklist for Drilling & Initial Completion Operations.

Authorized by BCER