

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2140
Inspection Date: 2026-06-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100100328
Well ID: 32173
Well Name: OVV HZ SWAN LAKE 06-22-077-14
Location: DLS: 06-22-077-14

Permit: 100100328
Well ID: 32174
Well Name: OVV HZ SWAN LAKE A06-22-077-14
Location: DLS: A06-22-077-14

Permit: 100100328
Well ID: 32175
Well Name: OVV HZ SWANLAKE B06-22-077-14
Location: DLS: B06-22-077-14

Permit: 100100328
Well ID: 32176
Well Name: OVV HZ SWANLAKE C06-22-077-14
Location: DLS: C06-22-077-14

Permit: 100100328
Well ID: 32177
Well Name: OVV HZ SWANLAKE D06-22-077-14
Location: DLS: D06-22-077-14

Permit: 100100328
Well ID: 32178
Well Name: OVV HZ SWANLAKE E06-22-077-14
Location: DLS: E06-22-077-14

Permit: 100100328
Well ID: 32179
Well Name: OVV HZ SWANLAKE F06-22-077-14
Location: DLS: F06-22-077-14

Permit: 100100328
Well ID: 32180
Well Name: OVV HZ SWANLAKE G06-22-077-14
Location: DLS: G06-22-077-14

Permit: 100100328
Well ID: 32181
Well Name: OVV HZ SWANLAKE H06-22-077-14
Location: DLS: H06-22-077-14

Permit: 100100328
Well ID: 32182
Well Name: OVV HZ SWANLAKE I06-22-077-14
Location: DLS: I06-22-077-14

Permit: 100100328
Well ID: 32183
Well Name: OVV HZ SWANLAKE J06-22-077-14
Location: DLS: J06-22-077-14

Permit: 100100328
Well ID: 32184
Well Name: OVV HZ SWANLAKE K06-22-077-14
Location: DLS: K06-22-077-14

Permit: 100102214
Facility ID: 00026351
Facility Name: OVV SWAN LAKE 06-22-077-14 001
Facility Type: Well Facility
Location: DLS: 06-22-077-14

Authorized by BCER