

Inspection Report

Permit Holder: Bonterra Energy Corp.
Inspection: 2026-2156
Inspection Date: 2026-06-26
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1410HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Pig Station- No concerns at time of inspection.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (Spec blinds in place). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site-No concerns at time of inspection.
Note- Tank exterior lining coming off and falling into secondary containment (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100051005
Well ID: 20374
Well Name: BONTERRA SIRIUS D- 057-L/094-A-15
Location: NTS: D- 057-L/094-A-15

Permit: 100051005
Facility ID: 00021715
Facility Name: BONTERRA BUICKCREEK D-057-L/094-A-15 001
Facility Type: Well Facility
Location: NTS: D- 057-L/094-A-15



Inspection Number: 2026-2156
Inspection Date: 2026-06-26

Letter ID: L2603081
Letter Date: 2026-06-29

Authorized by BCER