

## Inspection Report

Permit Holder: Saba Oil & Gas Ltd.  
Inspection: 2026-2158  
Inspection Date: 2026-06-23  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-H2O injection with cover. No chain and lock on wellhead valve handles. No flowline disconnect from the wellhead.

-No SCVF

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100001315  
Well ID: 01022  
Well Name: SABA O&G BOUNDARY 16-34-085-14  
Location: DLS: 16-34-085-14

---

Authorized by BCER