

Inspection Report

Permit Holder: Bonterra Energy Corp.
Inspection: 2026-2159
Inspection Date: 2026-06-26
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1450HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles mostly chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Note- Insulated blanket around wellhead decaying and falling off (See attached).

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site-No concerns at time of inspection.
Note- Tank exterior lining coming off and falling into secondary containment (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055575
Well ID: 21578
Well Name: BONTERRA BUICK A- 007-L/094-A-15
Location: NTS: A- 007-L/094-A-15

Permit: 100055575
Facility ID: 00022290
Facility Name: BONTERRA BUICK A-007-L/094-A-15 001
Facility Type: Well Facility
Location: NTS: A- 007-L/094-A-15

Authorized by BCER