

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2160
Inspection Date: 2026-06-26
Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informe inspection of surface equipment on site.

Performed inspection of location at 1505HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043795
Well ID: 18191
Well Name: CNRL BUICK D- 086-E/094-A-15
Location: NTS: D- 086-E/094-A-15

Authorized by BCER