

## Inspection Report

Permit Holder: Bonterra Energy Corp.  
Inspection: 2026-2171  
Inspection Date: 2026-06-26  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1630HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Pig Station- No concerns at time of inspection.

Lease Equipment: Wellhead Suspended. Barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (Spec blinds in place). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site-No concerns at time of inspection.  
Note- Tank exterior lining coming off and falling into secondary containment (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100051716  
Well ID: 20861  
Well Name: BONTERRA ET AL BEAVERTAIL D- 004-E/094-A-15  
Location: NTS: D- 004-E/094-A-15

Permit: 100051716  
Facility ID: 00021952  
Facility Name: BONTERRA BEAVERTAIL D-004-E/094-A-15 001  
Facility Type: Well Facility  
Location: NTS: D- 004-E/094-A-15



Inspection Number: 2026-2171  
Inspection Date: 2026-06-26

Letter ID: L2603100  
Letter Date: 2026-06-29

---

Authorized by BCER