

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-2180  
Inspection Date: 2026-06-24  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

b-73-E/94-H-1:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.

-No SCVF

-All equipment remains in place.

b-A73-E/94-H-1:

-wellhead only, valves chained and locked. No SCVF

-As per the Guidelines, there needs to be a 10-meter radius around the suspended well, that is free of vegetation.

lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100015404  
Well ID: 08600  
Well Name: CNRL DRAKE B- 073-E/094-H-01  
Location: NTS: B- 073-E/094-H-01

Permit: 100056602  
Well ID: 21879  
Well Name: CNRL DRAKE B-A073-E/094-H-01  
Location: NTS: B-A073-E/094-H-01

Permit: 100056602  
Facility ID: 00022421  
Facility Name: CNRL DRAKE B-073-E/094-H-01 001  
Facility Type: Well Facility  
Location: NTS: B- 073-E/094-H-01

---

Authorized by BCER