

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2186
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

c-10-J/94-H-1:

-wellhead chained and locked. Flowline is disconnected from the wellhead.
Majority of equipment remains in place. Some equipment has been removed. 400 bbl tanks onsite also.

-No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100030814
Well ID: 14171
Well Name: CNRL LADYFERN C- 010-J/094-H-01
Location: NTS: C- 010-J/094-H-01

Permit: 100030814
Facility ID: 00019802
Facility Name: CNRL LADYFERN C-010-J/094-H-01 001
Facility Type: Well Facility
Location: NTS: C- 010-J/094-H-01

Permit: 100033017
Facility ID: 00007146
Facility Name: CNRL LADYFERN C-010-J/094-H-01 003
Facility Type: Compressor Station
Location: NTS: C- 010-J/094-H-01

Permit: 100036830
Facility ID: 00007245
Facility Name: CNRL LADYFERN C-010-J/094-H-01 005
Facility Type: Compressor Station
Location: NTS: C- 010-J/094-H-01

Permit: 100058800
Facility ID: 00007602
Facility Name: CNRL LADYFERN C-010-J/094-H-01 007
Facility Type: Battery Site
Location: NTS: C- 010-J/094-H-01

Permit: 100030712
Pipeline Project ID: 000009864
Segment IDs (Location): 1 (From NTS: C- 010-J/094-H-01 To NTS: D- 086-G/094-H-01), 3 (From NTS: C- 010-J/094-H-01 To NTS: C- 010-J/094-H-01)

Permit: 100035446
Pipeline Project ID: 000011230
Segment IDs (Location): 1 (From NTS: C- 010-J/094-H-01 To NTS: C- 010-J/094-H-01)

Permit: 100038660
Pipeline Project ID: 000012197
Segment IDs (Location): 1 (From NTS: C- 010-J/094-H-01 To NTS: C- 008-J/094-H-01)

Authorized by BCER