

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2194
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

d-29-H/94-H-1:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Equipment remains in place. No SCVF

d-A29-H/94-H-1:

-wellhead valves chained and locked. No SCVF. Equipment remains in place.

d-B29-H/94-H-1:

-wellhead only valve handles removed. No SCVF.

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100031638
Well ID: 14367
Well Name: CNRL LADYFERN D- 029-H/094-H-01
Location: NTS: D- 029-H/094-H-01

Permit: 100042669
Well ID: 17753
Well Name: CNRL LADYFERN D-A029-H/094-H-01
Location: NTS: D-A029-H/094-H-01

Permit: 100042879
Well ID: 17869
Well Name: CNRL LADYFERN D-B029-H/094-H-01
Location: NTS: D-B029-H/094-H-01

Permit: 100033969
Facility ID: 00007186
Facility Name: CNRL LADYFERN D-029-H/094-H-01 002
Facility Type: Satellite Battery
Location: NTS: D- 029-H/094-H-01

Permit: 100042669
Facility ID: 00020657
Facility Name: CNRL DRAKE D-029-H/094-H-01 003
Facility Type: Well Facility
Location: NTS: D- 029-H/094-H-01

Authorized by BCER