

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2196
Inspection Date: 2026-06-24
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead tied into a 400bbl tank. Then that tank is connected to a second 400bbl tank via a hose.

-the earthen berm around the two 400bbl tanks has no liner in it and does not appear to be large enough to contain 110% capacity of tank size. The thief hatch appears to be lifted on one of the 400bbl tanks.

-a wellhead cover sits off to the side of well, not covering the wellhead. No chain and lock on wellhead valves and no flowline disconnect.

lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001060
Well ID: 00810
Well Name: CNRL ET AL WILDMINT D- 045-A/094-H-02
Location: NTS: D- 045-A/094-H-02

Permit: 100001060
Facility ID: 00018463
Facility Name: CNRL WILDMINT D-045-A/094-H-02 001
Facility Type: Well Facility
Location: NTS: D- 045-A/094-H-02

Authorized by BCER