

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2198
Inspection Date: 2026-06-25
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-walked into wellsite as access was too muddy.

-vegetation growing up and around the wellhead. No 10-meter radius around the wellhead free of vegetation as per the Guidelines.

-wellhead valves chained and locked. Flowline is disconnected from the wellhead. Electric pumpjack remains in place disconnected.

Lease and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001987
Well ID: 01497
Well Name: CNRL PEEJAY D- 043-H/094-A-15
Location: NTS: D- 043-H/094-A-15

Authorized by BCER