

## Inspection Report

Permit Holder: R360 Environmental Solutions Canada Inc.

Inspection: 2026-2207

Inspection Date: 2026-07-02

Inspection Outcome: Inspected

### Inspection Comment:

Well 100/10-31-81-17

Signage no concerns.

SCV no venting observed.

Well not in operation, disconnected from operating system.

No staining around wellhead area.

All plugs and caps in place.

Injection Well 102/10-31-81-17

Signage no concerns.

SCV no venting observed.

No staining around wellhead area.

All plugs and caps in place.

Well running at 16,653 KPA at time of inspection.

Injection well is used for produced water and non-hazardous waste.

Injection pressure is running at between 16,700 KPA and 16,900 KPA and is continually measured and recorded.

Annual pacer isolation test scheduled for August/September 2026.

Annual disposal operation hours and maximum injection pressure values are submitted on the monthly BS-S18 disposal statement.

Annual reservoir pressure tests are being conducted, and hydraulic isolation logs are done every 5 years.

Injected fluid is being metered as per requirements.

Secondary containment around site buildings, no concerns.

Site is visually tidy and organized.

No concerns identified at time of site inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074143

Well ID: 27395

Well Name: R360 CANADA TOWER 08-31-081-17

Location: DLS: 08-31-081-17

Permit: 100074166

Facility ID: 00008648

Facility Name: R360 CANADA SOUTH TAYLOR 08-31-081-17 002

Facility Type: Oil Sales Meter

Location: DLS: 08-31-081-17

---

Authorized by BCER