

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-2208
Inspection Date: 2026-07-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA#12901 and 12921 (A) - July 2, 2026: 10:46 hrs.

Wellheads (2x): surface casing valve open, LEL measured (Altair-5x), and flow observed. SCVA valves are being reported/monitored/maintained by company as required.

Both wellheads are in suspended status.

Signage posted is compliant to standards.

Well Facility: Is in suspended status.

Storage: double wall tank on metal stand, SDS labels present, and grounded.

Flowline valves were disconnected to WA# 12921 (wellhead valve handles were all chained and locked) and WA# 12901 - flowlines were connected to the wellhead with control valves in the closed position. The majority of wellheads valve handles were chained and locked.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100026851
Well ID: 12901
Well Name: PETRONAS BEG A- 085-F/094-G-01
Location: NTS: A- 085-F/094-G-01

Permit: 100026853
Well ID: 12921
Well Name: PETRONAS BEG A-A085-F/094-G-01
Location: NTS: A-A085-F/094-G-01



Inspection Number: 2026-2208
Inspection Date: 2026-07-02

Letter ID: L2603163
Letter Date: 2026-07-02

Authorized by BCER