

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2221
Inspection Date: 2026-07-02
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1402HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in 1 min).

Building entry test- No alarms on personal monitor. Building Inactive.

Pig station: deactivated.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100030802
Well ID: 14197
Well Name: TOURMALINE NIG A- 042-H/094-H-04
Location: NTS: A- 042-H/094-H-04

Authorized by BCER