

Inspection Report

Permit Holder: Bonterra Energy Corp.
Inspection: 2026-2222
Inspection Date: 2026-07-02
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1424HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Inactive. Records indicated well has not produced since May 2025. No barricades in place (Limited risk due to isolated location). Signage in place. Most Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tank and secondary containment on site-No concerns at time of inspection.

Note- Inactive wells will need to be suspended within 60 days of the well being inactive.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100056237
Well ID: 21816
Well Name: BONTERRA ET AL UMBACH B- 022-E/094-H-03
Location: NTS: B- 022-E/094-H-03

Permit: 100056237
Facility ID: 00022392
Facility Name: BONTERRA UMBACH B-022-E/094-H-03 001
Facility Type: Well Facility
Location: NTS: B- 022-E/094-H-03



Inspection Number: 2026-2222
Inspection Date: 2026-07-02

Letter ID: L2603179
Letter Date: 2026-07-03

Authorized by BCER