

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-2224  
Inspection Date: 2026-07-02  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1534HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: D-20-D Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

D-A20-D Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Test Separator Building entry test- No alarms on personal monitor.

Pig Station- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076205  
Well ID: 28338  
Well Name: CNRL HZ NIG D- 020-D/094-H-03  
Location: NTS: D- 020-D/094-H-03

Permit: 100079896  
Well ID: 30153  
Well Name: CNRL HZ NIG D-A020-D/094-H-03  
Location: NTS: D-A020-D/094-H-03

Permit: 100076205  
Facility ID: 00018012  
Facility Name: CNRL NIGCREEK D-020-D/094-H-03 001  
Facility Type: Well Facility  
Location: NTS: D- 020-D/094-H-03

---

Authorized by BCER