

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-2225  
Inspection Date: 2026-07-02  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1610HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: A-8-D Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

A-A8-D Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test (Glove partially filled in 2 min). Building entry test- No alarms on personal monitor.

A-C8-D Well appears active. ESD appears open. Barricades in place. Signage in place. Wellhead near completely covered in insulated blanket. Surface casing vent flow test- Minor Flow detected from glove test (Glove filled in 2 min). Building entry test- No alarms on personal monitor.

A-D8-D Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test (Glove filled in 1 min). Performed bubble test at 1615-1625- No bubbles observed during bubble test. Building entry test- No alarms on personal monitor.

Pig Station- No concerns at time of inspection.

Test Separator Building entry test- No alarms on personal monitor. No concerns at the time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077368  
Well ID: 28868  
Well Name: CNRL HZ W BUICK A- 008-D/094-H-03  
Location: NTS: A- 008-D/094-H-03

Permit: 100077384  
Well ID: 28869  
Well Name: CNRL HZ W BUICK A-A008-D/094-H-03  
Location: NTS: A-A008-D/094-H-03

Permit: 100077909  
Well ID: 29133  
Well Name: CNRL HZ W BUICK A-C008-D/094-H-03  
Location: NTS: A-C008-D/094-H-03

Permit: 100103207  
Well ID: 34159  
Well Name: CNRL HZ BUICKCREEKWEST A-D008-D/094-H-03  
Location: NTS: A-D008-D/094-H-03

Permit: 100077368  
Facility ID: 00025825  
Facility Name: CNRL NORTHERNMONTNEY A-008-D/094-H-03 001  
Facility Type: Well Facility  
Location: NTS: A- 008-D/094-H-03

Permit: 100077384  
Facility ID: 00025826  
Facility Name: CNRL NORTHERNMONTNEY A-008-D/094-H-03 002  
Facility Type: Well Facility  
Location: NTS: A- 008-D/094-H-03

Permit: 100077385  
Facility ID: 00025827  
Facility Name: CNRL BUICK CREEK WEST A-008-D/094-H-03 003  
Facility Type: Well Facility  
Location: NTS: A- 008-D/094-H-03

---

Authorized by BCER