

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-2233
Inspection Date: 2026-07-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Road #: 02629 Segment #: 001 and 002 - July 3, 2026: 9:24 hrs.

Inspected: 0 - 20km Atick Road. - road prism/surface is maintained to standards.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078060

Road Number: 02629

Segment IDs (Location): 001 (From NTS: C- 065-H/094-G-02 To NTS: D- 008-H/094-G-02), 002 (From NTS: D- 008-H/094-G-02 To NTS: C- 065-H/094-G-02)

Authorized by BCER