

## Inspection Report

Permit Holder: Bonterra Energy Corp.  
Inspection: 2026-2273  
Inspection Date: 2026-07-07  
Inspection Outcome: Inspected

### Inspection Comment:

Site 04-20-082-13 was inspected at or about 0950 hours, it was 16 & sunny. The following was included in the inspection:

Access and signage: Signage clear and legible, rutted, dry

Site: Wellsite clean and dry

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Riser & pig stations: chains, grounds, - no concerns

Production tank has been replaced and the site is clean of any debris.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100031595  
Well ID: 14617  
Well Name: BONTERRA CLAYHURST 04-20-082-13  
Location: DLS: 04-20-082-13

---

Authorized by BCER