

## Inspection Report

Permit Holder: VERMILION ENERGY INC.  
Inspection: 2026-2275  
Inspection Date: 2026-07-07  
Inspection Outcome: Inspected

### Inspection Comment:

Site 08-35-081-14 was inspected at or about 1030 hours, it was 20 & sunny. The following was included in the inspection:  
Access and signage: Signage clear and legible  
Site: Wellsite clean and no vegetation concerns  
Wellheads: Bull plugs, SCV, locks, leaks, - SCV flow detected on all except E.  
Critical valves locked, Operator made aware  
Meter/separator buildings: locks, leaks, caps, vents, - handle above sight glass  
leak in separator building - Operator attended and corrected  
Chemical tanks: leaks, grounds, caps, - no concerns  
Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118466  
Well ID: 50000  
Well Name: VERMILION HZ MICA 08-35-081-14  
Location: DLS: 08-35-081-14

Permit: 100118466  
Well ID: 50001  
Well Name: VERMILION HZ MICA A08-35-081-14  
Location: DLS: A08-35-081-14

Permit: 100118466  
Well ID: 50002  
Well Name: VERMILION HZ MICA B08-35-081-14  
Location: DLS: B08-35-081-14

Permit: 100118466  
Well ID: 50003  
Well Name: VERMILION HZ MICA C08-35-081-14  
Location: DLS: C08-35-081-14

Permit: 100118466  
Well ID: 50004  
Well Name: VERMILION HZ MICA D08-35-081-14  
Location: DLS: D08-35-081-14

Permit: 100118466  
Well ID: 50005  
Well Name: VERMILION HZ MICA E08-35-081-14  
Location: DLS: E08-35-081-14

Permit: 100118466  
Facility ID: 00028010  
Facility Name: VERMILION MICA 08-35-081-14 001  
Facility Type: Well Facility  
Location: DLS: 08-35-081-14

Permit Holder: VERMILION ENERGY INC.

---

Authorized by BCER