

Inspection Report

Permit Holder: Cardinal Energy Ltd.
Inspection: 2026-2276
Inspection Date: 2026-07-07
Inspection Outcome: Inspected

Inspection Comment:

Site 09-35-081-14 was inspected at or about 1045 hours, it was 20 & sunny. The following was included in the inspection:
Access and signage: Signage clear and legible
Site: Wellsite clean and no vegetation concerns
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100054880
Well ID: 21401
Well Name: CARDINAL MICA 09-35-081-14
Location: DLS: 09-35-081-14

Permit: 100056929
Facility ID: 00007581
Facility Name: CARDINAL MICA 09-35-081-14 002
Facility Type: Battery Site
Location: DLS: 09-35-081-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER