

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-2277  
Inspection Date: 2026-07-08  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Access inspected. Noted matting and culvert debris in the ditch near Salt Creek Bridge (see pictures). Pipe also stored along roadside near pad (see pictures).

\*Please send inspector most recent bridge inspection for the Salt Creek Bridge.

See non-compliance for washing on access.

Well pad clean.

Wellhead inspected. Signage clear and legible. No SCV flow observed. Wellhead barricaded. Meter building inspected.

Chem tanks inspected.

Pig barrels inspected.

Associated pipeline well vegetated.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061567  
Well ID: 23277  
Well Name: OVV ECOG ET AL HZ BRASSEY B-A016-C/093-P-10  
Location: NTS: B-A016-C/093-P-10

Permit: 100061567  
Facility ID: 00023035  
Facility Name: OVV DEEPBASIN B-016-C/093-P-10 001  
Facility Type: Well Facility  
Location: NTS: B- 016-C/093-P-10



Permit: 100067191  
Road Number: 00600  
Segment IDs (Location): 001 (From NTS: B- 016-C/093-P-10 To NTS: D- 086-K/093-P-07)

---

Authorized by BCER