

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2278
Inspection Date: 2026-07-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1035HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. Standing water beside lease entrance (See attached). No erosion sediment or water runoff concerns.

Lease Equipment: C-B12-A Well appears active. ESD appears open. No barricades in place. Signage in place. Surface casing vent flow test-Minor flow detected from glove test. Building entry test- No alarms on personal monitor.

C-A12-A Well appears active. ESD appears open. No barricades in place. Signage in place. Surface casing vent flow test-Minor flow detected from glove test. Building entry test- No alarms on personal monitor.

C-12-A Well appears active. ESD appears open. No barricades in place. Signage in place. Surface casing vent flow test-Flow detected from glove test (glove filled in less than 30 seconds). Performed bubble test from 1055HRS-1105HRS- No bubbles observed. Occasional odors downwind of wellhead- No alarms on personal monitor. Building entry test- No alarms on personal monitor.

Separator building entry test- No alarms on personal monitor.

Tanks on site-No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

Note: Consider barricades around wellheads due to increased risk with multi-well pad.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100105589
Well ID: 36623
Well Name: CNRL HZ NIG CREEK C- 012-A/094-H-04
Location: NTS: C- 012-A/094-H-04

Permit: 100105589
Well ID: 36624
Well Name: CNRL HZ NIG CREEK C-A012-A/094-H-04
Location: NTS: C-A012-A/094-H-04

Permit: 100105589
Well ID: 36625
Well Name: CNRL HZ NIG CREEK C-B012-A/094-H-04
Location: NTS: C-B012-A/094-H-04

Permit: 100108168
Facility ID: 00026989
Facility Name: CNRL NIG CREEK C-012-A/094-H-04 001
Facility Type: Well Facility
Location: NTS: C- 012-A/094-H-04

Authorized by BCER