

## Inspection Report

Permit Holder: Cardinal Energy Ltd.  
Inspection: 2026-2279  
Inspection Date: 2026-07-07  
Inspection Outcome: Inspected

### Inspection Comment:

Site 13-04-082-14 was inspected at or about 1110 hours, it was 20 & sunny. The following was included in the inspection:  
Access and signage: Signage clear and legible  
Site: Wellsite clean and no vegetation concerns  
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns  
Meter/separator buildings: locks, leaks, caps, vents, - no concerns  
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100082543  
Well ID: 30834  
Well Name: CARDINAL HZ MICA A13-04-082-14  
Location: DLS: A13-04-082-14

Permit: 100083546  
Well ID: 31837  
Well Name: CARDINAL HZ MICA C13-04-082-14  
Location: DLS: C13-04-082-14

Permit: 100082543  
Facility ID: 00026158  
Facility Name: CARDINAL OTHERAREAS 13-04-082-14 001  
Facility Type: Well Facility  
Location: DLS: 13-04-082-14

Permit: 100083546  
Facility ID: 00026219  
Facility Name: CARDINAL CLIENTCLASSIFIED 13-04-082-14 003  
Facility Type: Well Facility  
Location: DLS: 13-04-082-14

Permit Holder: Cardinal Energy Ltd.



Inspection Number: 2026-2279  
Inspection Date: 2026-07-07

Letter ID: L2603268  
Letter Date: 2026-07-09

---

Authorized by BCER