

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2280
Inspection Date: 2026-07-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1205HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pump jack & well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Stuffing box has absorbing rag wrapped & taped around stuffing box (see attached). Surface casing vent flow test- No Flow detected from glove test.

Test Separator building entry test- No alarms on personal monitor. odors inside building. LEL alarm on personal monitor from open tubing fitting (Missing cap) & audible hissing coming from fitting.

Pig station- Pig barrel safety chain is not attached to PAV (see attached).

Tank on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048660
Well ID: 19615
Well Name: CNRL ET AL FIREWEED C- 031-H/094-A-13
Location: NTS: C- 031-H/094-A-13

Permit: 100050866
Facility ID: 00011717
Facility Name: CNRL FIREWEED C-031-H/094-A-13 001
Facility Type: Satellite Battery
Location: NTS: C- 031-H/094-A-13

Authorized by BCER