

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2282
Inspection Date: 2026-07-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1255HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Pig Station- missing plug on 1/4 turn valve on pigging station (See attached).

Tank on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055540
Well ID: 21602
Well Name: CNRL HZ W BUICK B- 097-E/094-A-14
Location: NTS: B- 097-E/094-A-14

Permit: 100055540
Facility ID: 00022302
Facility Name: CNRL BUICKCREEKWEST B-097-E/094-A-14 001
Facility Type: Well Facility
Location: NTS: B- 097-E/094-A-14



Inspection Number: 2026-2282
Inspection Date: 2026-07-07

Letter ID: L2603274
Letter Date: 2026-07-09

Authorized by BCER