

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-2285  
Inspection Date: 2026-07-07  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1405HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: B-80-E- Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in 1 min).

B-A80-E- Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. No Positive isolation. Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Pig Station- Pig barrel safety chain is not attached to PAV.

Tank on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016183  
Well ID: 08844  
Well Name: CNRL BERKLEY W BUICK B- 080-E/094-A-14  
Location: NTS: B- 080-E/094-A-14



Permit: 100027557  
Well ID: 13075  
Well Name: CNRL HZ W BUICK B-A080-E/094-A-14  
Location: NTS: B-A080-E/094-A-14

---

Authorized by BCER