

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2286
Inspection Date: 2026-07-07
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1435HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease (lease appears to have recently been sprayed). No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Calibration tags on meters indicate last calibration was done in June 2023.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048398
Well ID: 19095
Well Name: CNRL HZ W BUICK C-A046-E/094-A-14
Location: NTS: C-A046-E/094-A-14

Permit: 100048398
Facility ID: 00021063
Facility Name: CNRL BUICKCREEKWEST C-046-E/094-A-14 002
Facility Type: Well Facility
Location: NTS: C- 046-E/094-A-14

Authorized by BCER



Inspection Number: 2026-2286
Inspection Date: 2026-07-07

Letter ID: L2603279
Letter Date: 2026-07-09