Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2287
Inspection Date: 2026-07-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1448HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Production records indicate well has not flowed since May 2022. No barricades in place (Limited risk due to isolated location). Signage in place. No positive isolation. Valve handles not chained, locked & secure or removed. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Building out of service.

Tank on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100027703
Well ID: 13179
Well Name: CNRL HZ W BUICK A-A067-E/094-A-14
Location: NTS: A-A067-E/094-A-14

Authorized by BCER