

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2288
Inspection Date: 2026-07-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1500HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. Location may have recently been sprayed No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Strong odors in proximity to wellhead. H2S alarm on personal monitor detected around master valve on wellhead.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005480
Well ID: 03882
Well Name: CNRL W BUICK A- 067-E/094-A-14
Location: NTS: A- 067-E/094-A-14

Authorized by BCER