

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-2289  
Inspection Date: 2026-07-07  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1519HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Pig Station- No concerns at time of inspection.

Tank on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100046767  
Well ID: 19162  
Well Name: CNRL HZ W BUICK C- 078-E/094-A-14  
Location: NTS: C- 078-E/094-A-14

Permit: 100046767  
Facility ID: 00021086  
Facility Name: CNRL BUICKCREEKWEST C-078-E/094-A-14 001  
Facility Type: Well Facility  
Location: NTS: C- 078-E/094-A-14

---

Authorized by BCER



Inspection Number: 2026-2289  
Inspection Date: 2026-07-07

Letter ID: L2603284  
Letter Date: 2026-07-09