

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2291
Inspection Date: 2026-07-07
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1615HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Building out of service.

Pig Station- No concerns at time of inspection. Occasional odors downwind of Pig launcher (no alarms on personal monitor).

Note: various surface equipment discarded/stored at West side of location (see attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100056314
Well ID: 21881
Well Name: TOURMALINE BUICK A- 077-J/094-A-11
Location: NTS: A- 077-J/094-A-11

Permit: 100056314
Facility ID: 00022422
Facility Name: TOURMALINE BUICKCREEK A-077-J/094-A-11 001
Facility Type: Well Facility
Location: NTS: A- 077-J/094-A-11



Inspection Number: 2026-2291
Inspection Date: 2026-07-07

Letter ID: L2603286
Letter Date: 2026-07-09

Authorized by BCER