

Inspection Report

Permit Holder: Cardinal Energy Ltd.
Inspection: 2026-2296
Inspection Date: 2026-07-07
Inspection Outcome: Inspected

Inspection Comment:

Site 02-04-082-14 was inspected at or about hours, it was 26 & sunny. The following was included in the inspection:
Access and signage: Signage clear and legible
Site: Wellsite clean and no vegetation concerns
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100023239
Well ID: 11775
Well Name: CARDINAL MICA 02-04-082-14
Location: DLS: 02-04-082-14

Permit: 100023239
Facility ID: 00019448
Facility Name: CARDINAL MICA 02-04-082-14 001
Facility Type: Well Facility
Location: DLS: 02-04-082-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER