

## Inspection Report

Permit Holder: VERMILION ENERGY INC.  
Inspection: 2026-2298  
Inspection Date: 2026-07-07  
Inspection Outcome: Inspected

### Inspection Comment:

Site 08-18-081-14 was inspected at or about 1240 hours, it was 26 & sunny. The following was included in the inspection:  
Access and signage: Signage clear and legible  
Site: Wellsite clean and no vegetation concerns  
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves unlocked - Operator contacted, attended and locked.  
Meter/separator buildings: locks, leaks, caps, vents, - no concerns  
Riser & pig stations: chains, grounds, - missing chain - notified chain will be added - a follow up inspection will be done

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100080735  
Well ID: 30629  
Well Name: VERMILION HZ DOE 08-18-081-14  
Location: DLS: 08-18-081-14

Permit: 100100276  
Facility ID: 00026235  
Facility Name: VERMILION DOE 08-18-081-14 002  
Facility Type: Battery Site  
Location: DLS: 08-18-081-14

Permit Holder: VERMILION ENERGY INC.

---

Authorized by BCER